

Er. J.VARA PRASAD

BE, PGDCM, C. ENG. (i), FIV
MICA, MIE, M.I.STRUCT.E
CHARTERED ENGINEER,
APPROVED ENGINEER BY BOE - P.W.D & IN COLLECTOR'S PANEL
TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

283/35, 2nd Floor, Jai Hind Flats
Belly Area, Anna Nagar (West),
Chennai – 600 040.
Email : jvprasaad@gmail.com
CELL : 94433 79267, 99623 99199
Phone : 044 – 48611799

STATEMENT ACCOMPANYING FORM 'A' STRUCTURAL STABILITY

1. Name of the School : **GOOD WORD PUBLIC SCHOOL**
 2. Location street No. Ward No : Survey No.524/1A1,524/1C1,524/1C2,524/1D,
Name of place, (i.e.) corporation : 524/1E1,524/1E2,524/2A524/2B,524/2C,526/1
Municipality /Panchayath / (As Informed / Reported) Konimedu, Opposite to
Panchyath Office, Pammadhukulam, Redhills,
Chennai – 600 052.
 3. Year of construction : **Block - A**
G. Floor : 2011 About 8 Years
F. Floor : 2012 About 7 Years
S. Floor : 2014 About 5 Years
Block - B:
G. Floor: 2016 About 3 Years
F. Floor: 2017 About 2 Years
S. Floor: 2019 – New
 4. Approximate cost of Construction : About Rs.140.00 Lacs
 5. Purpose for which the building is being used or proposed to be used : For Conducting SchoolClasses
 6. Purpose for which the building has hitherto been used : For Conducting SchoolClasses
 7. Details of construction of the building (particulars) of the foundation, soil specification of the various parts as under
 - a. Foundation : RCC Isolated Footing
 - b. Basement : Brick work in CM
 - c. Superstructure : RCC Columns, Brick wall in Cm
 - d. Floor &Roof ,are to be given : Cement Flooring & RCC Roof
 8. Period for which license is required : From **25.09.2019 to 24.09.2022**
FOR THREE YEARS ONLY
 9. No. of persons to be accommodated : About 1350 Pupils
(One Thousand Three Hundred Fifty Pupils Only)
- Place: Chennai
Date : 26.09.2019

For GOOD WORD PUBLIC SCHOOL


Correspondent

For GOOD WORD PUBLIC SCHOOL


Principal

J. VARA PRASAD
C. Eng. (i), MIE - MICA, M.I. Struct. E.,
Chartered Engineer
Approved Engineer in Collector's Panel,
Competent Person to issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Bally Area, Nr. Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell : 99623 99199, 94433 79627
Off.: 78583 94949, Ph : 044 2626 0799

FORM - B

STATEMENT TO ACCOMPANY THE REPORT OF STRUCTURAL SOUNDNESS

Location of the Building door No. Street Name & Name of the Place.	Age of the Building	No of storeys	Short Description of structure, steel RCC framed or load bearing masonry.
GOOD WORD PUBLIC SCHOOL Survey No.524/1A1,524/1C1,524/1C2,524/1D, 524/1E1,524/1E2,524/2A524/2B,524/2C,526/1 (As Informed / Reported) Konimedu, Opposite to Panchyath Office, Pammadhukulam, Redhills, Chennai - 600 052.			RCC Isolated Footing Brick work in CM RCC Columns, Brick wall in CM Cement Flooring & RCC Roof

Block - A : G. Floor : 2011 About 8 Years, F. Floor : 2012 About 7 Years, S. Floor : 2014 About 5 Years

Block - B : G. Floor: 2016 About 3 Years, F. Floor: 2017 About 2 Years, S. Floor: 2019 - New

Purpose for which The building is To be used	period for which the license is required	No. of persons accommodated.	Remarks
For Conducting School Classes	25.09.2019 to 24.09.2022 FOR THREE YEARS ONLY	About 1350 Pupils (One Thousand Three Hundred Fifty Pupils Only)	The Building is Structurally Sound

This Report does not include any Eventualities caused by Natural Calamities. We here by advise that the Periodical Repairs and Renovations Shall be carried out to the Entire Building Block regularly. Further Necessary fire fighting equipments should be kept in the premises and should be trained for operation. If any fire accident / Mishap occurs we are not held responsible. Structural Alteration / Deviation Should Not be Carried out to a part / whole Building without Prior Permission from the Competent Authority. Emergency Exit to be provided as per norms. All electrical points, wiring / Gadgets has to be checked properly and to be maintained periodically. **All Necessary safety standards has to be Strictly adhered.** If any violations is found at a later period after issue of this Report / License we are not held responsible and this Report gets cancelled. Further this Report covers the above said Building Blocks Only. Legal Aspects were not considered in this report.

J. VARA PRASAD
PGDCM, C.Eng., FIV., MIE., MICA., M.I. Struct. E.,
Chartered Engineer
Approved Engineer in Collector's Panel,
Competent Person to issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Belly Area, Nr. Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell : 99623 99199, 94433 79627
Off. : 78583 94949, Ph : 044 2626 0799


Place : Chennai

Dated : 26.09.2019

For GOOD WORD PUBLIC SCHOOL


Correspondent

For GOOD WORD PUBLIC SCHOOL


Principal

FORM - C

Form of Report of structural soundness under sub-section (4) of section 4 of
The Tamil Nadu public building (licensing) Act 1965 (Tamil Nadu act 1 of 1965) Referred to in rule 4 of the
Tamil Nadu public (Licensing) Rules, 1966.

We have inspected the building mentioned in the statement and furnish below its salient technical
features:

1. Foundation:

- a. Depth below ground level : About 1. 2Mts.
- b. Nature of soil met with at
foundation level. : Clay Soil
- c. Pressure at foundation : About 15 Tons/sq.m
- d. Probable safe bearing capacity of
The soil strata met with at foundation :

2. Superstructure :

- a. Minimum stress in the most
Critical section of
Masonry and concrete :
- b. Nature of masonry and concrete
And its safe permissible stress :

We are of the Opinion that the building is structurally sound. A license can be granted for the period
from 25.09.2019 to 24.09.2022 (FOR THREE YEARS ONLY)

Place: Chennai.


Date : 26.09.2019

For GOOD WORD PUBLIC SCHOOL


Correspondent


J. VARA PRASAD
PGDCM., C.Eng., FIV., MIE., MICA., M.I. Struct. E.,
Chartered Engineer
Approved Engineer in Collector's Panel,
Competent Person to issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Belly Area, Nr. Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell : 99623 99199, 94433 79627
Off.: 78583 94949, Ph : 044 2626 0799

For GOOD WORD PUBLIC SCHOOL


Principal

Er. J.VARA PRASAD

BE, PGDCM, C. ENG. (i), FIV

MICA, MIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER BY BOE - P.W.D & IN COLLECTOR'S PANEL

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

283/35, 2nd Floor, Jai Hind Flats

Belly Area, Anna Nagar (West),

Chennai – 600 040.

Email :jvprasaad@gmail.com

CELL : 94433 79267, 99623 99199

Phone : 044 – 48611799

ANNEXURE TO "STATEMENT ACCOMPANYING FORM – A"

We have inspected the School Premises buildings, **GOOD WORD PUBLIC SCHOOL**, Survey No.

524/1A1,524/1C1, 524/1C2,524/1D, 524/1E1,524/1E2,524/2A524/2B,524/2C,526/1,(As Informed/ Reported)

Konimedu, Opposite to Panchyath Office, Pammadhukulam, Redhills, Chennai – 600 052.The following Building

is of **Block – A** : G. Floor : 2011 About 8 Years, F. Floor : 2012 About 7 Years S. Floor : 2014 About 5 Years

Block – B: G. Floor: 2016 About 3 Years, F. Floor: 2017 About 2 Years, S. Floor: 2019 – New is available. This

Report doesnot includeany other Buildings/Blocksor Structures Such as Compound wall Semi/ Non permanent

Structures either inGF or in any other floors etc.,We here by advise that the Periodical Repairs and Renovations

Shall be carriedout to the Entire Building Block regularly.

Further Necessary fire fightingequipments should be kept in the premises and should be trained for operation. If any fire accident / Mishap occurs we are not held responsible. Emergency exit to be provided as per norms. Structural Alteration / Deviation Should Not be carried out to any of the blocks for Whole Building Or any Part of Building Without Prior Permission from the Competent Authority. All Electrical points, wiring / Gadgets has to be checked properly and to be maintained regularly. Periodic water proofing treatment is to be done as per standards. **This Report does not cover any Structure / Partly completed Structure or building under construction. Any Further additional construction either in G.F or in any other Floors / Blocks the necessary approvals / structural design / stability has to be Subsequently obtained.** All Electrical Panel Boards/Main Switches / cables, Generator, Electrical Maintenance Room has to be kept in safety with lock & key position. Access to open terraces to be kept in Lock & key Position. The UG sump, manholes, OHT, Inspection Chamber, septic Tank Openings as to be Sealed with cover slab. If any above mentioned Aspects were found violated at a later date after issue of this Report / License we are not held responsible and this Report gets cancelled. Legal Aspects were not considered in this report.

Place:Chennai

Date : 26.09.2019

J. VARA PRASAD
PGDCM., C.Eng., Fiv., MIE., MICA., M.I. Struct. E.,
Chartered Engineer
Approved Engineer in Collector's Panel,
Competent Person to issue Stability Certificate's
No. 283/35, 2nd Floor, Jai Hind Flats,
Belly Area, Nr. Chinmaya School,
Anna Nagar West, Chennai - 600 040,
Cell : 99623 99199, 94433 79627
Off.: 78583 94949, Ph : 044 2626 0799

For GOOD WORD PUBLIC SCHOOL


Correspondent

For GOOD WORD PUBLIC SCHOOL


Principal